

DIAGNOSTIC REPORT

VIN: 1T9NSHA83KR825039

Model Year: 2019

Manufacturer:

COMPONENT	FAULT CODES	4 TOTAL / 2 ACTIVE / 2 INACTIVE
-----------	-------------	---------------------------------

ENGINE #1 - J1939

ACTIVE FAULT CODES (1)

Vehicle Make: Cummins	Fault Description: EGR 1 Valve 1 Control 1	SPN 2791
ECM Serial Number: 74405343	FMI Description: Out of CAL	FMI: 13
ECM Model: 6B u14D067	Count: 3	

INACTIVE FAULT CODES (2)

Fault Description: Undefined	SPN 6802
FMI Description: Condition Exists	FMI: 31
Count: 48	

Fault Description: Engine Protection Torque Derate	SPN 1569
FMI Description: Condition Exists	FMI: 31
Count: 1	

TRANSMISSION #1 - J1939

ACTIVE FAULT CODES (1)

Vehicle Make: N/A	Fault Description: Undefined	SPN 190
ECM Serial Number: N/A	FMI Description: Special Instructions	FMI: 14
ECM Model: N/A	Count: 126	

INACTIVE FAULT CODES (0)

None

UNKNOWN/RESERVED (SA)

ACTIVE FAULT CODES (0)

ECM Serial Number:	None
ECM Model:	

INACTIVE FAULT CODES (0)

None

INSTRUMENT CLUSTER #1 -

ACTIVE FAULT CODES (0)

ECM Serial Number:	None
ECM Model:	

INACTIVE FAULT CODES (0)

None

SHIFT CONSOLE - PRIMARY -

ACTIVE FAULT CODES (0)

ECM Serial Number:	None
ECM Model:	

INACTIVE FAULT CODES (0)

None

DIAGNOSTIC REPORT

VIN: 1T9NSHA83KR825039

Model Year: 2019

Manufacturer:

PARAMETERS

ENGINE #1 - J1939

Rated Horsepower	158 BHP	Engine Rated RPM	Not Available
MIL Status	Off	Fuel Level	N/A
Battery Voltage	14.25 V	Ignition Voltage	Not Available
Engine RPM	749 RPM	Vehicle Speed	0 mph
Throttle Position	0 %	Brake Switch	Depressed
Clutch Switch	Depressed	Engine Operating State	Engine Stopped
Engine Intake Air Temperature	Not Available	Engine Intake Air Pressure	Not Available
Barometric Pressure	Not Available	Coolant Level	100 %
Coolant Temperature	147.2 °F	Oil Level	Not Available
Oil Temperature	Not Available	Oil Pressure	54.0 psi
DPF Status	Regen not Needed	Regen Status	N/A
DPF Active Regen Inhibited Status	Inhibited	DPF Active Regen Inhibited Due to Inhibit Switch	Not Inhibited
DPF Regen Inhibit Switch	N/A	DPF Regen Force Switch	Active
Exhaust Temperature 1	N/A	Exhaust Temperature 2	N/A
Exhaust Temperature 3	N/A	DPF Intake Temperature	N/A
DPF Outlet Temperature	N/A	DPF Differential Pressure	N/A

TRANSMISSION #1 - J1939

Battery Voltage	N/A	Ignition Voltage	N/A
Input Shaft Speed	715 RPM	Output Shaft Speed	0 RPM
Oil Level	Not Available	Oil Life Remaining	N/A
Oil Temperature	101.4 °F	Service Indicator	N/A
Range Selected	N/A	Range Attained	N/A

LIFE DATA

ENGINE #1 - J1939

Distance	58455.28 mi	Hours	15261.45 hr
Fuel Used	22637.7 gal	Average Fuel Economy	N/A
Engine Idle Hours	8262.20 hr	Engine Idle Fuel Used	8734.7 gal
PTO Hours	0.00 hr	PTO Fuel Used	0.0 gal
DPF Number of Inhibited Active Regen	Not Available	DPF Number of Manual Active Regen	Not Available
DPF Fuel Used	85.3 gal		

DIAGNOSTIC REPORT

VIN: 1T9NSHA83KR825039

Model Year: 2019

Manufacturer:

TRIP DATA

ENGINE #1 - J1939

Distance	58464.29 mi	Fuel Used	22550.3 gal
Average Fuel Rate	1.48 gal/hr	Idle Time	N/A
Vehicle Idle Fuel Used	8734.7 gal	Cruise	N/A
Cruise Fuel Used	0.0 gal	DPF Active Regen Time	N/A
DPF Number of Active Regens	N/A	DPF Used	N/A
Vehicle Speed Limit	24 mph	Cruise Control Speed Limit	Not Available