

DIAGNOSTIC REPORT

VIN: 1T9NSHA86KR825052

Model Year: 2019

Manufacturer:

COMPONENT	FAULT CODES	6 TOTAL / 1 ACTIVE / 5 INACTIVE
-----------	-------------	---------------------------------

ENGINE #1 - J1939

ACTIVE FAULT CODES (1)

Vehicle Make: Cummins	Fault Description: ECL	SPN 111
ECM Serial Number: 74431066	FMI Description: Data Valid but below Normal Operating Range - Moderately Severe Level	FMI: 18
ECM Model: 6B u14D067	Count: 3	
VIN: 1T9NSHA8QKR825052		

INACTIVE FAULT CODES (5)

Fault Description: ECL	SPN 111
FMI Description: Data Valid but below Normal Operational Range - Most Severe Level	FMI: 1
Count: 2	

Fault Description: Engine Protection Torque Derate	SPN 1569
FMI Description: Condition Exists	FMI: 31
Count: 5	

Fault Description: Catalyst Tank Level	SPN 1761
FMI Description: Abnormal Update Rate	FMI: 9
Count: 28	

Fault Description: Catalyst Tank Temperature	SPN 3031
FMI Description: Abnormal Update Rate	FMI: 9
Count: 28	

Fault Description: Catalyst Tank Reagent Quality	SPN 3364
FMI Description: Abnormal Update Rate	FMI: 9
Count: 28	

TRANSMISSION #1 - J1939

ACTIVE FAULT CODES (0)

Vehicle Make: N/A	None
ECM Serial Number: N/A	
ECM Model: N/A	
VIN: N/A	None

INACTIVE FAULT CODES (0)

UNKNOWN/RESERVED (SA)

ACTIVE FAULT CODES (0)

ECM Serial Number:	None
ECM Model:	

INACTIVE FAULT CODES (0)

None

INSTRUMENT CLUSTER #1 -

ACTIVE FAULT CODES (0)

ECM Serial Number:	None
--------------------	------

DIAGNOSTIC REPORT

VIN: 1T9NSHA86KR825052

Model Year: 2019

Manufacturer:

COMPONENT FAULT CODES 6 TOTAL / 1 ACTIVE / 5 INACTIVE

ECM Model: **INACTIVE FAULT CODES (0)**

None

SHIFT CONSOLE - PRIMARY - ACTIVE FAULT CODES (0)

ECM Serial Number: None

ECM Model: **INACTIVE FAULT CODES (0)**

None

PARAMETERS

ENGINE #1 - J1939

Rated Horsepower	158 BHP	Engine Rated RPM	Not Available
MIL Status	Off	Fuel Level	N/A
Battery Voltage	8.10 V	Ignition Voltage	Not Available
Engine RPM	0 RPM	Vehicle Speed	0 mph
Throttle Position	0 %	Brake Switch	Depressed
Clutch Switch	Depressed	Engine Operating State	Engine Stopped
Engine Intake Air Temperature	Not Available	Engine Intake Air Pressure	Not Available
Barometric Pressure	Not Available	Coolant Level	0 %
Coolant Temperature	59.0 °F	Oil Level	Not Available
Oil Temperature	Not Available	Oil Pressure	0.0 psi
DPF Status	Regen not Needed	Regen Status	N/A
DPF Active Regen Inhibited Status	Inhibited	DPF Active Regen Inhibited Due to Inhibit Switch	Not Inhibited
DPF Regen Inhibit Switch	N/A	DPF Regen Force Switch	Active
Exhaust Temperature 1	N/A	Exhaust Temperature 2	N/A
Exhaust Temperature 3	N/A	DPF Intake Temperature	N/A
DPF Outlet Temperature	N/A	DPF Differential Pressure	N/A

TRANSMISSION #1 - J1939

Battery Voltage	N/A	Ignition Voltage	N/A
Input Shaft Speed	0 RPM	Output Shaft Speed	0 RPM
Oil Level	Not Available	Oil Life Remaining	N/A
Oil Temperature	59.6 °F	Service Indicator	N/A
Range Selected	N/A	Range Attained	N/A

DIAGNOSTIC REPORT

VIN: 1T9NSHA86KR825052

Model Year: 2019

Manufacturer:

LIFE DATA

ENGINE #1 - J1939

Distance	49576.18 mi	Hours	17555.85 hr
Fuel Used	23783.6 gal	Average Fuel Economy	N/A
Engine Idle Hours	10450.80 hr	Engine Idle Fuel Used	10603.6 gal
PTO Hours	0.00 hr	PTO Fuel Used	0.0 gal
DPF Number of Inhibited Active Regen	Not Available	DPF Number of Manual Active Regen	Not Available
DPF Fuel Used	87.3 gal		

TRIP DATA

ENGINE #1 - J1939

Distance	49586.63 mi	Fuel Used	23694.7 gal
Average Fuel Rate	1.35 gal/hr	Idle Time	N/A
Vehicle Idle Fuel Used	10603.6 gal	Cruise	N/A
Cruise Fuel Used	0.0 gal	DPF Active Regen Time	N/A
DPF Number of Active Regens	N/A	DPF Used	N/A
Vehicle Speed Limit	24 mph	Cruise Control Speed Limit	Not Available